

APPENDIX A

NOTICE OF VIOLATION

South Carolina Electric and Gas Company  
V. C. Summer

License No. CPPR-94

Based on the NRC inspection August 5-8, 1980, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

As required by Criterion V of Appendix B to 10 CFR 50 and implemented by the FSAR, Paragraph 17.1.5, "Activities affecting quality shall be prescribed by documented instructions, procedures,...and shall be accomplished in accordance with those instructions, procedures,..." Daniel Construction Company Construction Procedure WP-VII-09 Revision 10 "Installation of Piping", Paragraph 3.2.5 requires pipe weld end preparation and fit-up to conform to GAI Drawing C-301-002.

Contrary to the above, a fit-up condition involving excessive mismatch not in accordance with the requirements of GAI Drawing C-301-002 was accepted by Daniel Construction Company quality control inspector for Weld FW-14 on ISO CC-25 in the component cooling system.

This is an infraction.

8011210673