


# YANKEE ATOMIC ELECTRIC COMPANY



Rowe, Massachusetts 01367

July 8, 1977

Regulatory  
Mr. J. P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

FILE CY

*ML*

Subject: Reportable Occurrence 50-29/77-31/03L  
Loop Seal Radiation Monitor Failure

Dear Mr. O'Reilly:

In accordance with Technical Specifications, Section 6.9.4.b, the attached Licensee Event Report is hereby submitted.

Very truly yours,

Herbert A. Autio  
Plant Superintendent

RMM/mid

Enclosure:

- cc: [30] Director, Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555
- [3] Director, Office of Management Information & Program Control  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8011240

274

5