



CONNECTICUT YANKEE ATOMIC POWER COMPANY

HADDAM NECK PLANT

RR #1, BOX 127E, EAST HAMPTON, CONN. 06424

January 5, 1981

U. S. Nuclear Regulatory Commission
Region 1
Office of Inspection and Enforcement
631 Park Avenue
King of Prussia, Pennsylvania 19406

Attn: Mr. Boyce Grier,
Director

Reference: Facility Operating License No. DPR-61
Docket No. 50-213
Reportable Occurrence LER 80-17/3L

Dear Mr. Grier:

This correspondence forwards the Licensee Event Report for Reportable Occurrence LER 80-17/3L, required to be submitted within thirty (30) days, pursuant to the requirements of procedure SUR 5.1-71, Reactor Core Power Surveillance for Four Loop Operation.

An additional three copies of the report are attached.

Very truly yours,

Richard H. Graves
Station Superintendent

RHG:RZT/jhb
Attachment: LER 80-17/3L

cc: Dir., Office of Inspection & Enforcement, Washington, D. C. (3)
Dir., Office of Management Info. & Program Control, Wash., D. C. (30)
USNRC c/o Document Management Branch, Washington, D. C. (1)

REGISTRATION
SERVICES UNIT

1981 JAN 9 AM 9 31

REGISTRATION
SERVICES
BRANCH

81010906265