

TENNESSEE VALLEY AUTHORITY

MEMPHIS, TENNESSEE 38101

400 Chestnut Street Tower II

January 9, 1981



Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNIT 2 - INCORRECT INSULATION WEIGHT USED IN PIPING  
ANALYSIS - NCR SQN CEB 8008 - THIRD INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector  
C. R. McFarland on April 24, 1980, in accordance with 10 CFR 50.55(e).  
Interim reports were submitted on May 23, and October 16, 1980. We expect  
to submit our next report by February 26, 1981.

The as-constructed insulation drawings have been completed. TVA is  
reviewing these drawings against the completed analyses to determine if any  
reanalysis is required.

If you have any questions, please get in touch with D. L. Lambert at  
FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager  
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director ✓  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

B019  
S 1/0

8101180 485

5