

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION V

1990 N. CALIFORNIA BOULEVARD
SUITE 202, WALNUT CREEK PLAZA
WALNUT CREEK, CALIFORNIA 94526

Docket Nos. 50-89 50-163

December 23, 1980

General Atomic Company P. O. Box 81608 San Diego, California 92138

Attention: Mr. H. N. Wellhouser, Director

Nuclear Materials Control Division

Gentlemen:

Subject: NRC Inspection of Mark I and Mark F Reactors

This refers to the inspection conducted by Mr. A. D. Johnson of this office on December 15-17, 1980, of activities authorized by NRC License Nos. R-38 and R-67, and to the discussions of our findings held by Mr. Johnson with Mr. Wellhouser and Dr. Whittemore and other members of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspectors.

No items of noncompliance with NRC requirements were identified within the scope of this inspection.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you believe to be proprietary, it is necessary that you submit a written application to this office, within 20 days of the date of this letter, requesting that such information be withheld from public disclosure. The application must include a full statement of the reasons why it is claimed that the information is proprietary. The application should be prepared so that ary proprietary information identified is contained in an enclosure to the application, since the application without the enclosure will also be placed in the Public Document Room. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

Should you have any questions concerning this inspection, we will be glad to discuss them with you.

Sincerely,

Reactor Operations and
Nuclear Support Branch

Enclosure: IE Inspection Report Nos. 50-89/80-02 and 50-163/80-02

cc w/o enclosure: Mr. W. R. Mowry, GA Licensing Administrator