POST OFFICE BOX 2951 . BEAUMONT, TEXAS 77704 W

GULF STATES UTILITIES COMPAN

AREA CODE 713 838-3843

November 3, 1980

RBG -Files G9.5, G9.33.1

Mr. K. V. Seyfrit, Director U.S. Nuclear Regulatory Commission Region IV, Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, TX 76011

Dear Mr. Seyfrit:

River Bend Station - Units 1 & 2 Refer to: RIV Docket No. 50-458/Bulletin 80-16 Docket No. 50-459/Bulletin 80-16

As per our conversation with our NSSS vendor (G.E.), the investigation of I&E Bulletin 80-16 has not been completed. A deadline date of November 24, 1980, has been set to assure you a final response on the subject of "Potential Misapplication of Rosemount Incorporated Models 1151 and 1152 Pressure Transmitters with either 'A' or 'D' Output Codes." Our response on November 24, 1980, will conclude all correspondence for I&E Bulletin 80-16.

Sincerely,

E. Linn Draper, Jr. Vice President - Technology

ELD/RJK/mea