



Omaha Public Power District

1623 HARNEY • OMAHA, NEBRASKA 68102 TELEPHONE 536-4000 AREA CODE 402

January 26, 1981

Mr. Darrell G. Eisenhut, Director
U. S. Nuclear Regulatory Commission
Office of Nuclear Reactor Regulation
Division of Licensing
Washington, D.C. 20555

Reference: Docket No. 50-285

Dear Mr. Eisenhut:

Enclosure 11 to Omaha Public Power District's letter to the Commission dated December 31, 1980, provided a report entitled "Review of Conformance to the TMI Task Action Plan for Control Room Habitability". As discussed in the District's letter, this report was to be revised. Accordingly, the revised report is attached. Enclosure 1 provides a summary of changes to the report and Enclosure 2 is the complete, revised report.

Sincerely,

W. C. Jones
Division Manager
Production Operations

WCJ/KJM/TLP:jmm

Enclosures

cc: LeBoeuf, Lamb, Leiby & MacRae
1333 New Hampshire Avenue, N.W.
Washington, D.C. 20036

Acc. 1/1

810 2050 444

P

LIST OF MODIFICATIONS
TO CONTROL ROOM HABITABILITY REPORT
ISSUED 12/19/80

<u>Page Number</u>		<u>Modification</u>
<u>12/19/80</u> <u>Report</u>	<u>Rev. A</u> <u>Report</u>	
13-14	13-14	Modified Table 2.0 to reflect clarified railway information
49	50	Added statement saying that Tables 4.4.1 and 4.4.2 show chemicals currently on-site but do not represent limits
50-63	51-64	Changed page numbers
55	56	Deleted paragraph discussing nitrogen
56	57	Deleted paragraph discussing bulk aluminum
63	-	Deleted paragraph referring to Table 4.5.4.1
64-65	-	Deleted Table 4.5.4.1
66	65	Added paragraph on aircraft transport limits
66-67	66-67	Revised Section 4.5.5 to reflect abandonment of north/south rail route
68	68	Changed north/south track to Transcontinental Transport
72	72	Changed east/west track to Local Transport
90	90	Changed distance in last sentence to 2.2 miles
93	93	Revised Table 6.1.2.2 to reflect new railway information
94	94	Added statement "(north/south track abandoned)" to Figure 6.1.2.1
95	95	Revised Figure 6.1.2.2 to reflect new location
98	98	Deleted "one-quarter inch" at top of page
109	109	Revised ammonia concentrations
112	112	} Changed distance to control room to 3500 m
120	120	
124	124	
117	117	Revised chloride concentrations
121	121	Changed north/south to east/west
122	122	Revised hydrochloric acid concentration

LIST OF MODIFICATIONS TO CONTROL ROOM HABITABILITY REPORT ISSUED 12/19/80 (CONTINUED)

<u>Page Number</u>		<u>Modification</u>
<u>12/19/80 Report</u>	<u>Rev. A Report</u>	
129	129	Changed 3 year burnup to 3 cycle burnup
130	130	
131	131	
133	133	
134	134	
161	161	
162	162	
137	137	Corrected Gas Decay Tank volume from 3130 scf to 2875 scf
143	143	Revised note (c) from "40 days following accident" to "for 30 days following accident"
153	153	Corrected containment hydrogen purge rate from 5 scfm to 25 scfm (typo). Revised note (b) from "40 days" to "5 days" Revised note (a) from "year" to "cycle"
164	165	Revised thyroid dose, modified paragraph at bottom of page 164 and at top of page 165 and added assumption (5)
170	170	Corrected Regulatory Guide 1.3 to 1.4 (typo)
180	180	Deleted paragraph (2)