

TENNESSEE VALLEY AUTHORITY  
CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

February 2, 1981

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET  
NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE  
REPORT SQRO-50-327/8106

The enclosed report provides details concerning the failure to perform  
a surveillance requirement following maintenance on a critical systems  
structures and components valve. This event resulted in failure to comply  
with Surveillance Requirement 4.0.5 and is reported under Sequoyah unit 1  
Technical Specification 6.9.1.13.e.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. J. Green  
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)  
Office of Management Information and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Director (40)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Mr. Bill Lavalley  
Nuclear Safety Analysis Center  
Palo Alto, California 94303

NRC Inspector, Sequoyah

A002  
5  
1/1

8102010112  
S