

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	T	N	S	N	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4					5				
7	8	LICENSEE CODE							14	LICENSE NUMBER										25	LICENSE TYPE					30	CAT NO								

CON'T

REPORT SOURCE L 6 0 5 0 0 0 3 2 7 7 0 1 1 1 4 8 1 8 0 2 0 5 8 1 9

7 8 60 61 DOX KET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

07 | At 1005 (c) on 1/14/81, Vital Inverter 2-II failed rendering vital instrument power

03 board 2-II inoperative. There was no effect on public health or safety. Previous

0 4 | occurrences - 14 - total occurrences for all eight inverters.

0	5	
---	---	--

06 _____

07 _____

08 _____

7 8 9 10 11 12 13 14 15 16 17 18 19 20

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE

0 9 E D 11 E 12 A 13 G E N E R A 14 F 15 Z 16

(17) LER/NO REPORT NUMBER [8 | 1] [—] [0 | 0 | 5] [/] [0 | 3] [L] [—] [0]
 21 22 23 24 25 26 27 28 29 30 31 32

ACTION TAKEN: [A] (8) [C] (19)
EFFECT ON PLANT: [Z] (20)
SHUTDOWN METHOD: [Z] (21)
HOURS: [0] [0] [0] [0] (22)
ATTACHMENT SUBMITTED: [N] (23)
NPRD-4 FORM SUB.: [N] (24)
PRIME COMP. SUPPLIER: [L] (25)
COMPONENT MANUFACTURER: [5] [3] [7] [9] (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The following two components failed while in service: ClA capacitor in the AlO Power

1 1 Supply and the RB-8 Control card. These components were replaced and the inverter

1 2 | was returned to service at 1755 (c) on 1/14/81. Preparations are in progress to

1	3	replace this inverter with a new inverter identical to those installed on unit 1.
---	---	---

14

FACILITY STATUS		% POWER		OTHER STATUS (11)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (12)
1	5	B	(28)	1 0 0 (29)	NA	A (31) Operator observation

ACTIVITY CONTENT						AMOUNT OF ACTIVITY (35)		LOCATION OF RELEASE (36)	
RELEASED OF RELEASE									
1	G	7	(22)	7	(23)	NA			NA

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION
1		
2		
3		
4		
5		
6		
7		
8		
9		
10		
11		
12		
13		
14		
15		
16		
17		
18		
19		
20		
21		
22		
23		
24		
25		
26		
27		
28		
29		
30		
31		
32		
33		
34		
35		
36		
37		
38		
39		
40		
41		
42		
43		
44		
45		
46		
47		
48		
49		
50		

PERSONNEL INJURIES		80
NUMBER	DESCRIPTION (41)	

LOSS OF OR DAMAGE TO FACILITY (43)

7 8 9 10 NA

PURCHASER'S NAME (45)

ISSUED DESCRIPTION (45)

NRC USE ONLY

Name of Preparer: J. M. McGriff/S. G. Maddox

Phone: (615) 842-8317

8102100 546