

CONTROL BLOCK: ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	J	A	F	1	2	0	0	-	0	0	0	0	-	0	0	0	3	4									4					5																																																					
7	8	9							14										15										25										26										30										57										CAT										58									
		LICENSEE CODE																	LICENSE NUMBER																				LICENSE TYPE																																																	

CON'T

REPORT SOURCE: 01 L 05000333701248130220819
60 61 68 69 74 75 80
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal shutdown, while conducting surveillance to satisfy TS 4.5.C.1, the

0 3 | HPCI System flow square root computation module was found out of calibration.

0 4 | When flow indication was at a rated value of 4250 gpm the actual flow would have

0 5 | been 4203 gpm. The system was not required to be operable. No significant

0 6 | hazard existed.

0 7 |

0 8 |

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE					
0	9	S	F	E	E	N	S	T	R	Y	Z						
7	8	9	10	11	12	13	14	15	16	17	18	19	20				
SERIAL REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
17		8	1		0	1	3		0	3							
21	22	23	24	25	26	27	28	29	30	31	32						
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
E	Z	Z	Z	Z	Z	0	0	0	N	Y	N	G	0	8	0		
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48		

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10	Instrument drift is believed to be the cause. Following calibration the
11	instrument was returned to service. No additional action is required.
12	
13	
14	

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

FACILITY STATUS (35) 0 0 0 (29) NA OTHER STATUS (30) METHOD OF DISCOVERY (31) B Surveillance DISCOVERY DESCRIPTION (32)

ACTIVITY CONTENT RELEASED OF RELEASE (33) 7 (34) NA AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES NUMBER (37) 0 0 0 (38) Z (39) NA TYPE DESCRIPTION

PERSONNEL INJURIES NUMBER (40) 0 0 0 (41) NA DESCRIPTION

LOSS OF OR DAMAGE TO FACILITY TYPE (42) Z (43) NA DESCRIPTION

PUBLICITY ISSUED (44) N (45) NA DESCRIPTION NRC USE ONLY

NAME OF PREPARER W. Verne Childs

PHONE. 315-342-3840

81-02250052