NORTHROP

January 26, 1981



U.S. Nuclear Regulatory Commission Region V 1990 N. California Boulevard Suite 202. Walnut Creek Plaza

Walnut Creek, California 94596

Attention: J. L. Crews, Chief Reactor Operations and Nuclear Support Branch

Reference: Docket No. 50-187

Gentlemen:

8102260278

Pursuant to the provisions of Section 2.201, of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires us to submit to your office, within twenty-five (25) days of the date of your notice, a written statement or explanation in reply including (1) corrective steps which have been taken by us and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved.

Contrary to the requirements of 10 CFR 50, Paragraph 50.54 (i-1), the periodic and systematic performance evaluations for the licensed Reactor Supervisor had not been performed and not documented as required by Paragraph VII of the NRC approved Operator Requalification Training Program.

- Corrective steps which have been taken and results achieved;
 - Systematic performance evaluations for the licensed Reactor Supervisor has been performed and documented as required.
- (2) Corrective steps which were taken to avoid further violations; Periodic file system has been established to review the status of all Reactor personnel's training and performance evaluations.
- (3) Date when full compliance was achieved was January 13, 1981.

If you should have any questions concerning this letter, please contact the undersigned.

Watto E frankel

Walter E. Crandall, Chairman Corporate Radiation Committee

Northrop Corporation . Northrop Research and Technology Center . One Research Park . Palos Verdes Peninsula, Calif. 90274