

BOSTON EDISON COMPANY

TELECOPY MESSAGE

To: 215-337-5324
Telephone Number

Date/Time: 3/3/81 / 1230 hrs.

To: Director, Region I
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

From: Pilgrim Nuclear Power Station
RFD #1 Rocky Hill Road
Plymouth, MA 02360



Subject: PROMPT REPORTABLE OCCURRENCE
Docket Number 50-293; License DPR-35
Assigned LER Number 81-006/01X-0

Event Description: On February 19, 1981 the ORC reviewed the station's alleged omission in the scheduling of eleven(11) once per cycle instrumentation. The ORC immediately assigned station personnel to investigate and report their findings to station management. As a result of the conclusion drawn from the investigation, the oversight was verified.

Cause and Corrective Action: This omission was the result of a misinterpretation by station personnel of the special circumstances which must be applied to the definition of "Once per Cycle" testing as it applies to instrumentation testing (i.e. that the surveillance interval may not exceed a specified time period). Nine(9) of these eleven tests have

Facility Status:	<u>0</u> % Thermal MW
c) Routine Startup _____	g) Shutdown <u>X</u>
d) Routine Shutdown _____	h) Refueling _____
e) Steady State _____	i) Other _____
f) Load Changing _____	j) Not Applicable _____

A written follow-up report will be sent within two weeks.

NRC person notified Mr. J. Johnson Prepared by Mr. M. Thomas McLoughlin
been performed during our present outage. The remaining two(2) will be completed prior to startup following this outage.

Mail (2) copies to: 8103090624
Office of Management Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

5
A002/01