

SEABROOK STATION  
Engineering Office:  
1671 Worcester Road  
Framingham, Massachusetts 01701  
(617) - 872 - 8100

February 23, 1981

SBN-152  
Ref SBU-42515  
T.F. Q 2.2.2



U.S. Nuclear Regulatory Commission  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Attention: Office of Inspection and Enforcement

Reference: 1. Docket No. 50-443 and 50-444  
2. Telecon of 1/26/81 between L. Narrow and John DeVincentis YAEC


Subject: Potentially Reportable 10 CFR 50.55 (e) Interim Report on  
Improper Non-Destructive Examinations

Dear Sir:

On Monday January 26, 1981 I reported a potentially significant deficiency associated with improper non-destructive examinations that we consider a potentially reportable item under 10 CFR 50.55 (e). This interim report is being filed in accordance with the thirty day reporting requirements of 10 CFR 50.55 (e).

An investigation is in progress at the Seabrook site to determine if a significant deficiency exists for this item. The investigation is scheduled to be completed by March 27, 1981. Upon the completion of the investigation, an evaluation will be conducted to the criteria of 10 CFR 50.55 (e) to determine if a significant deficiency exists. At that time we will either verbally inform you that a significant deficiency does not exist, or a formal report in accordance with the requirements of 10 CFR 50.55 (e) will be submitted. We consider this item to be a potentially reportable item until completion of the testing and evaluation program.

Very truly yours,

  
John DeVincentis  
Project Manager

JDV:tan

cc: Director of Inspection and  
Enforcement  
USNRC, Washington, DC 20555

3019  
3  
1/10