



United States Department of the Interior

GEOLOGICAL SURVEY
Water Resources Division
1819 North Meridian Street
Indianapolis, Indiana 46202
(317)-269-7101

50-367

March 23, 1981

Mr. M. David Lynch
Licensing Branch No. 1
Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Lynch:

During the weeks of February 23 and March 2, 1981, the following U.S. Geological Survey wells were developed and tested to insure that they are open to the aquifer:

GM-1	GM-39	D-5A	G-10	106
GM-2	GM-40	D-6A	23A	107
GM-3	GM-41	D-7A	23B	108
GM-4A	GM-42	D-8	24	109
GM-4B	GM-43	G-1	25	221-24
GM-4C	GM-44	G-2	26	222-183
GM-5	GM-45	G-4	27	222-65
GM-6	GM-46	G-4A	101	222-28
GM-7B	D-1A	G-6	102	223-115
GM-8	D-2A	G-7	103	223-20
GM-9	D-3A	G-8	104	224-55
GM-38	D-4A	G-9	105	

All wells except #107 were found to be open. Well #107 is at least partially plugged and does not appear to be responding to water-level changes in the aquifer. This well will be deactivated and replaced.

Wells D-1, D-4, D-5, D-6, and D-7 were removed during this maintenance period. Wells D-2 and D-3 will also be removed. All these wells have already been replaced by deeper wells at the same locations.

If you have any questions concerning this work, please feel free to call Lee Watson or David Cohen at (317)-269-7107.

Sincerely yours,

Dennis K. Stewart
District Chief

D004
S/O

8104010 396

A