

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION II

101 MARIETTA ST., N.W., SUITE 3100 ATLANTA, GEORGIA 30303

FEB 27 1981

Alabama Power Company ATTN: R. P. McDonald

Vice President-Nuclear Generation

P. O. Box 2641

Birmingham, AL 35291

Gentlemen:

SUBJECT: Report Nos. 50-348/81-03 and 50-364/81-04

This refers to the routine safety inspection conducted by W. H. Bradford of this office on January 1-31, 1981, of activities authorized by NRC Operating License Nos. NPF-2 and NPF-8 for the Farley facility, and to the discussion of our findings held with W. G. Hairston at the conclusion of the inspection.

Areas examined during the inspection and our findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspectors.

Within the scope of this inspection, no violations or deviations were disclosed.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you (or your contractor) believe to be proprietary, it is necessary that you make a written application within 20 days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

Richard CV Lewis, Acting Director Resident & Reactor Project Inspection

Branch

Enclosure: (See Page 2)

8104020764



Enclosure: Inspection Report Nos. 50-348/81-03 and 50-364/81-04

cc w/encl:

- W. O. Whitt, Executive Vice President
- F. L. Clayton, Jr., Senior Vice President
- H. O. Thrash, Manager-Nuclear Generation
- O. D. Kingsley, Jr., Manager, Nuclear Engineering and Technical Services
- J. W. McGowan, Manager-Operations Quality Assurance
- W. G. Hairston, III, Plant Manager
- W. C. Petty, Manager-Quality Assurance (Design and Construction)
- R. E. Hollands, Jr., QA Supervisor