

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401  
1750 Chestnut Street Tower II

April 10, 1981

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET  
NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE  
REPORT SQRO-50-327/81011

The enclosed report provides details concerning the inoperability of  
vital instrument power board 1-I.

Vital instrument power board 1-I being declared inoperable resulted in entering  
the action statement of limiting condition for operation 3.8.2.1 and is  
reported in accordance with Sequoyah unit 1 Technical Specification 6.9.1.13.b.

Sequoyah Licensee Event Reports (LER's) are transmitted to your office by  
the Division of Nuclear Power central office. Recently, a Sequoyah Compliance  
Staff (ISEG) review of LER's discovered that this LER was apparently lost  
in the mail between Sequoyah Nuclear Plant and the central office and was  
therefore never transmitted to your office. This LER is now being transmitted  
beyond the 30-day reporting time.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. J. Green  
Director of Nuclear Power

Enclosure (3)  
cc (Enclosure):  
Director (3)  
Office of Management Information and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Director (40)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Mr. Bill Lavalley  
Nuclear Safety Analysis Center  
Palo Alto, California 94303

NRC Inspector, Sequoyah

A002  
51/1

8104170 407  
3