

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower II

April 10, 1981

Mr. James P. O'Reilly, Director  
U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT UNIT 1 - DOCKET  
NO. 50-327 - FACILITY OPERATING LICENSE DPR-77 - REPORTABLE OCCURRENCE  
REPORT SQRO-50-327/81014

The enclosed report provides details concerning test procedures for valves 1-FCV-62-72, 73, and 74. This event is reportable under Sequoyah unit 1 Technical Specification 6.9.1.13.b.

Sequoyah Licensee Event Reports (LER's) are transmitted to your office by the Division of Nuclear Power central office. Recently, a Sequoyah Compliance Staff (ISEG) review of Licensee Event Reports discovered that this LER was apparently lost in the mail between Sequoyah Nuclear Plant and the central office and was therefore never transmitted to your office. This LER is now being transmitted beyond the 30-day reporting time.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. J. Green  
Director of Nuclear Power

Enclosure (3)

cc (Enclosure):

Director (3)  
Office of Management Information and Program Control  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Director (40)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Mr. Bill Lavallee  
Nuclear Safety Analysis Center  
Palo Alto, California 94303

NRC Inspector, Sequoyah

An Equal Opportunity Employer

A002  
5/1/1

5 8104170496