

U.S. NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT

REGION III

Report No. 50-341/80-01

Docket No. 50-341

License No. CPPR-87

Licensee: Detroit Edison Company
2000 Second Avenue
Detroit, MI 48226

Facility Name: Enrico Fermi Nuclear Power Station, Unit 2

Inspection At: Fermi Site, Monroe, MI

Inspection Conducted: January 1 - February 14, 1981

Inspectors: *W. S. Little*
B. H. Little

3/17/81

W. S. Little
P. M. Byron

3/17/81

Approved By: *W. S. Little*
W. S. Little, Chief
Reactor Projects Section 2C

3/17/81

Inspection Summary

Inspection on January 1 - February 14, 1981 (Report No. 50-341/81-01)
Areas Inspected: Routine preoperational inspection by resident inspector, consisting of a review of licensee action on previous inspection findings, IE Bulletin and Circular followup, plant tours and meetings with local public officials. The inspection involved a total of 123 inspector-hours onsite by two NRC inspectors including 12 inspector-hours onsite during off shifts.
Results: No items of noncompliance or deviations were identified.

DETAILS

1. Persons Contacted

*T. Alessi, Director Project QA
R. Lenart, Startup Engineer
H. Arora, Startup Director
*W. Fahrner, Manager Fermi 2 Project
J. Gessner, Assistant Project QA Director
S. Noetzel, Assistant Project Manager
H. Walker, Project QA Section Supervisor
*W. White, Plant Superintendent

*Denotes those attending weekly management meeting.

2. Licensee Action on Previous Inspection Findings

(Open) Unresolved item (341/80-23-01) "QA Level 1 Cable Pulling Problems." Subsequent licensee review of concerns expressed by Edison Audit Department identified apparent cable damage. Based on the initial review, the licensee issued an interim 10 CFR 50.55(e) report.

Followup and close out of this matter will be documented in a subsequent inspection report.

No items of noncompliance or deviations were identified.

3. IE Bulletin and Circular Followup

IE Bulletin issued during this period:

IE Bulletin 81-01, "Surveillance of Mechanical Snubbers."

IE Circulars issued during this period:

IE Circular No. 81-01, "Inoperable Seismic Monitoring Instrumentation."

IE Circular No. 81-02, "Performance of NRC-Licensed Individuals While on Duty."

The inspector verified the above Bulletin and Circulars have been received and undergoing licensee review. Followup and close out of these items will be documented in subsequent inspection reports.

No items of noncompliance or deviations were identified.

4. Information Meetings with Local Officials

A meeting with local public officials was held at Monroe, Michigan on January 22 and 30, 1981. NRC attendees were Senior Resident Inspector and Resident Inspector assigned to the Enrico Fermi 2

Nuclear plant. The meeting was held to acquaint local officials with the Resident Inspectors, the NRC mission and the NRC Inspection Program. Additional items discussed included local concerns, assistance and information sources, and the current status of Enrico Fermi 2 project.

Public Officials in attendance were:

J. Champion, Monroe Charter Supervisor
R. Norwood, Frenchtown Township Supervisor
D. Smith, Berlin Township Supervisor

5. Plant Tours

The inspector conducted plant tours of the reactor, auxiliary, turbine, and RHR buildings. The inspector observed shift turnovers, reviewed plant operating status including control room logs. The inspector also observed cable pulling activities and pipe hanger and pipe welding installation.

No items of noncompliance or deviations were identified.

6. Exit Interview

The inspector met with representatives (denoted in Paragraph 1) weekly and at the conclusion of the inspection period. The inspector summarized the scope of the inspection findings.