



Northern Indiana Public Service Company

Corporate Headquarters / 5255 Hohman Avenue / Hammond, Indiana 46320 / Tel: 853-5200 (219)

EUGENE M. SHORB
EXECUTIVE VICE PRESIDENT
AND CHIEF OPERATING OFFICER

April 8, 1981

U. S. Nuclear Regulatory Commission
Director of Reactor Construction
Inspection, O. I. E.
Washington, D. C. 20555



Subject: NRC IE Bulletin No. 80-09, "Hydramotor Actuators
Deficiencies"

Dear Sir:

My letter to you dated July 9, 1980, on the above subject explained Northern Indiana Public Service Company's (NIPSCO) position on this subject and suggested that NIPSCO will pursue this item as soon as engineering resumes or by June 1, 1981.

This is to inform you that engineering has not yet resumed and we are unable to obtain the information necessary to determine whether any safety-related systems or components that have been delivered to the Bailly site contain AH-90 or NH-90 series Hydramotor Actuators manufactured by ITT General Controls.

We will pursue this item after engineering resumes or respond by January 4, 1983.

Very truly yours,

EMS:cgs

cc: Mr. James G. Keppler, Regional Director
U. S. Nuclear Regulatory Commission, Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

8104270 400