

UNITED STATES

NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76011

Docket No. 99900063/81-01

03 MAR 1981



Pacific Pumps
Division Dresser Industries Inc.
Attn: Mr. D. B. Harney
President
5715 Bickett Street
Huntington Park, California 90255

Gentlemen:

This refers to the inspection conducted by H. W. Roberds of this office on January 20-23, 1981, of your facility at Huntington Park, California, and to the discussions of our findings with D. J. Moyer and members of your staff at the conclusion of the inspection.

This inspection was made as a result of the identification of nonconformances in centrifugal charging pumps that have been furnished to the Zion 1 and Sequoyah 2 nuclear power plants.

Areas examined during the inspection and our findings are discussed in the enclosed report. Within these areas, the inspection consisted of an examination of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, we found no instance where you failed to meet NRC requirements.

In accordance with Section 2.790 of the Commission's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter together with the enclosed inspection report will be placed in the Commission's Public Document Room. If this report contains any information that you believe to be proprietary, it is necessary that you make a written application to this office within twenty-five (25) days of the date of this letter, to withhold such information from public disclosure. The application must include a full statement of the reasons why it is claimed that any information is proprietary. The application should be prepared so that any proprietary information identified is contained in an enclosure to the application, since the application without the enclosure will also be placed in the Public Document Room. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.


8104280 253

Pacific Pumps

2

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,


Uldis Potapovs, Chief
Vendor Inspection Branch

Enclosure
Inspection Report No. 99900063/81-01