

NUCLEAR REGULATORY COMMISSION
REGION I

631 PARK AVENUE KING OF PRUSSIA, PENNSYLVANIA 19406

Docket Nos. 50-317 50-318 MAR 1 2 1981

Baltimore Gas and Electric Company ATTN: Mr. A. E. Lundvall, Jr. Vice President, Supply P.O. Box 1475 Baltimore, Maryland 21203

Gentlemen:

Subject: Inspection Number 50-317/81-02 and 50-318/81-02

This refers to the routine inspection comducted by Messrs. R. Architzel and C. Callahan of this office on January 5 - February 1, 1981 at the Calvert Cliffs Nuclear Power Plant, Lusby, Maryland of activities authorized by NRC License Nos. DPR-53 and DPR-69 and to the discussions of our findings held by Mr. R. Architzel with Mr. J. Carroll and others of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the Office of Inspection and Enforcement Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, measurements made by the inspector, and observations by the inspector.

Based on the results of this inspection, it appears that one of your activities was not conducted in full compliance with NRC requirements, as set forth in the Notice of Violation, enclosed herewith as Appendix A. This item of non-compliance has been categorized into the levels described in the Federal Register Notice (45 FR 66754) dated October 7, 1980. You are required to respond to this letter and in preparing your response, you should follow the instructions in Appendix A.

In accordance with Section 2.790(d) of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, documentation of findings of your control and accounting procedures for safeguarding special nuclear materials and your facility security measures for physical protection are deemed to be commercial or financial information within the meaning of 10 CFR 9.5(a)(4) and shall be subject to disclosure only in accordance with the provisions of 10 CFR 9.12; therefore, the pertinent section of the enclosed inspection report, will not be placed in the Public Document Room and will receive limited distribution.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Richard R. Weimig, Mief
Projects Branch #2, Division
of Resident and Project Inspection

Enclosures:

1. Appendix A, Notice of Violation

 Combined Office of Inspection and Enforcement Inspection Report Number 50-317/81-02 and 50-318/81-02*

cc w/encls:

R. M. Douglas, Manager, Quality Assurance (Without Page 7 of Report)#

L. B. Russell, Plant Superintendent (Without Page 7 of Report*

T. Sydnor, General Supervisor, Operations QA (Without Page 7 of Report)*

R. C. L. Olson, Principal Engineer (Without Page 7 of Report)*

J. A. Tiernan, Manager, Nuclear Power (Without Page 7 of Report)*

P. E. Denton, General Supervisor, Training and Technical Services (Without Page 7 of Report)*