

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

U 1 A L J M F 1 2 0 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 14 15 25 26 30 37 CAT 38

REPORT  
SOURCE

L 6 0 5 0 0 0 3 4 8 7 0 4 2 2 8 1 3 0 5 2 1 8 1 9  
60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 At 2210 on 4/22/81, the overtemperature-delta temperature instrumentation loop associ-  
0 3 ated with TI412C was declared inoperable upon the operator noting erratic readings on  
0 4 the TI412 indicator and receipt of a channel alert alarm. Tech. Spec. 3.3.1.1, in part,  
0 5 requires the TI412C instrumentation loop to be operable. Tech. Spec. 3.3.1.1 action  
0 6 statement requirements were met. The health and safety of the public were not affected.  
0 7

0 8 9

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
I A 11 E 12 G 13 I N S T R U 14 X 15 Z 16  
9 10 11 12 13 18 19 20  
17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.  
8 1 0 2 2 0 3 L 0  
21 22 23 24 25 27 28 29 30 31 32  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
C 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 N 24 N 25 W 1 2 0  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 This occurrence is attributable to a defective lead-lag card. The defective card was  
1 1 replaced and the channel was returned to service at 0510 on 4/23/81 following the  
1 2 successful performance of the surveillance test.  
1 3

1 4 9

1 5 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION  
E 28 0 9 8 29 NA A 31 Receipt of alarm  
7 8 9 12 13 44 45 46 80

1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE  
Z 33 Z 34 NA NA  
7 8 9 10 11 44 45 80

1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION  
0 0 0 37 Z 38 NA  
7 8 9 11 12 13 80

1 8 PERSONNEL INJURIES NUMBER DESCRIPTION  
0 0 0 40 NA  
7 8 9 11 12 13 80

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION  
Z 42 NA  
7 8 9 10 11 12 80

2 0 PUBLICITY DESCRIPTION  
N 44 NA  
7 8 9 10 80

NRC USE ONLY

NAME OF PREPARER W. G. Hairston, III

PHONE: (205)899-5156

8105270095