



Carolina Power & Light Company

FILE: NG-3513 (R)

May 15, 1981 A 8:12 SERIAL: NO-81-807

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303



H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
LICENSE NO. DPR-23
DOCKET NO. 50-261
RESPONSE TO IE BULLETIN 81-02

Dear Mr. O'Reilly:

In response to your letter of April 9, 1981, transmitting IE Bulletin 81-02, Carolina Power & Light Company submits the following response for H. B. Robinson Steam Electric Plant.

A thorough review has determined that there are no gate type valves of this manufacture in use, or maintained as spares at the Robinson Plant.

The manpower expended for this review and for the required report preparation was approximately eleven hours.

We trust that this satisfies the requirements of IE Bulletin 81-02.

Yours very truly,

B. J. Furr
Vice President
Nuclear Operations

SHC/bwb

cc: Mr. Victor Stello, Jr.

B. J. Furr, having been first duly sworn, did depose and say that the information contained herein is true and correct to his own personal knowledge or based upon information and belief.

My Commission expires:

2-25-85

Notary (Seal)

IE 11
5/10

8105270 264
Q