



Commonwealth Edison
Zion Generating Station
Shiloh Blvd. & Lake Michigan
Zion, Illinois 60099
Telephone 312/746-2084

May 14, 1981

Mr. James G. Keppler
Regional Director
Office of Inspection and Enforcement
Region III
U.S. Nuclear Regulatory Commission
Glen Ellyn, Illinois 60137




Reference: Zion Generating Station
Docket No. 50-295/DPR-39
Technical Specification, Section 6.6.2

Dear Mr. Keppler:

Enclosed please find Interim Reportable Occurrence Report No. 50-295/81-16 for Zion Generating Station.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 6.6.2.B.2 which states that conditions leading to operation in a degraded mode permitted by a limiting condition for operation require a 30 day written report.

Very truly yours,


K. L. Graesser
Superintendent
Zion Station

cc: J. Kohler/J. Waters

Enclosure: Interim Reportable Occurrence Report No. 50-295/81-16

8105280 228

5

MAY 18 1981

A002
511