

APPENDIX A

NOTICE OF VIOLATION

Middlesex Memorial Hospital
Middletown, Connecticut 06457
License No. 06-00649-03

Docket No. 30-1242

As a result of the inspection conducted on February 26, 1981, and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violation was identified:

Condition 19 of your license requires that licensed material be possessed and used in accordance with statements, representations and procedures contained in your application dated May 2, 1979.


Item III under the Radiation Safety Procedures contained in this application describes the procedure required for opening packages.

Contrary to this requirement, as of February 26, 1981, the procedure described was not used for opening packages containing iodine-131.

This is a Severity Level V Violation (Supplement VII).

Pursuant to the provisions of 10 CFR 2.201, Middlesex Memorial Hospital is hereby required to submit to this office within twenty-five days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Under the authority of Section 182 of the Atomic Energy Act of 1954, as amended, this response shall be submitted under oath or affirmation.

Dated 16 MAR 1981



John D. Kinneman, Chief
Materials Radiological Protection
Section

810529003