

MAY 22 1981

Central Mesabi Medical Center
ATTN: John A. Kayfer
Administrator
750 East 34th Street
Hibbing, Minnesota 55746

License No. 22-02403-01

Gentlemen:

This refers to the routine safety inspection conducted by Mr. John R. Madera of this office on May 12, 1981, of activities at Central Mesabi Medical Center authorized by NRC Byproduct Material License No. 22-02403-01 and to the discussion of our findings with Vincent J. Paciotti, M.D., Radiologist and Thomas D. Bergquist at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

This inspection included a review of the corrective action taken in response to our inspection conducted on September 27, 1978. We have no further questions regarding these matters.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

D. G. Wiedeman, Acting Chief
Materials Radiation Protection
Section 1

cc: Vincent J. Paciotti, M.D.
Radiology
Central Files
Reproduction Unit NRC 20L
PDR
NSIC

1E07
5/10

8106010-456

OFFICE	RIII	RIII				
SURNAME	Madera/so	Wiedeman				
DATE	5/19/81	5/20/81				