

**GULF STATES UTILITIES COMPANY**

POST OFFICE BOX 2951 • BEAUMONT, TEXAS 77704

AREA CODE 713 838-3843

June 1, 1981


Mr. Karl V. Seyfrit, Director  
U.S. Nuclear Regulatory Commission  
Region IV Office of Inspection & Enforcement  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Dear Mr. Seyfrit:

River Bend Station - Units 1 & 2  
Refer to: RIV  
Docket Nos. 50-458/I&E Bulletin 80-21  
50-459/I&E Bulletin 80-21

The River Bend Station NSSS vendor, General Electric (GE), has completed their review of I&E Bulletin No. 80-21 "Valve Yokes Supplied by Malcolm Foundry Company, Inc." GE has determined that within their scope of supply, River Bend Station has no active safety related valves or valve parts which were cast by Malcolm Foundry Company, Inc. This completes our response to the I&E Bulletin No. 80-21.

Sincerely,

  
E.L. Draper, Jr.  
Vice President-Nuclear Technology

FLD/ERG/cb

cc: U.S. Nuclear Regulatory Commission  
Office of Inspection & Enforcement  
Division of Reactor Construction Inspection  
Washington, D.C. 20555

8106080 298

Q

IE11  
5/10

IE-11