

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 N E C P R 1 2 d d - 0 0 0 0 - 0 d 3 4 1 1 1 1 4 5
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 38

1 6 0 5 0 0 0 2 9 8 7 1 1 1 7 8 0 8 1 2 1 4 8 d 9
8 REPORT SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

2 While in cold shutdown, RHR-MO-34A, the RHR "A" Loop suppression pool cooling in-
3 board throttle valve would not operate. This is a repetitive occurrence (ref. LER
4 76-14, 77-11 & 80-30). The "B" RHR Loop was operable as well as both diesel gener-
5 lators. The upstream valve was operable so that the "A" Loop could be used for LPCI
6 injection and for containment isolation purposes. RHR-MO-34A failed in the normally
7 closed position. There were no adverse affects to the public health and safety.

(RTS 3.5.B)

8 9 SYSTEM CAUSE CAUSE COMPONENT COMP. VALVE
CODE CODE SUBCODE CODE SUBCODE SUBCODE
1 C F 11 B 12 B 13 V A L V O P 14 A 15 Z 16
9 10 11 12 13 14 15 16
17 LER/RO EVENT YEAR SEQUENTIAL OCCURRENCE REPORT REVISION
NUMBER REPORT NO. NO. NO. NO. NO. NO.
8 0 0 4 7 0 3 L 0
21 22 23 24 25 26 27 28 29 30 31 32
ACTION FUTURE EFFECT SHUTDOWN HOURS ATTACHMENT NPRD-4 PRIME COMP COMPONENT
TAKEN ACTION ON PLANT METHOD NO. SUBMITTED FORM SUB. SUPPLIER MANUFACTURER
A 18 X 19 Z 20 Z 21 0 0 0 0 N 23 24 L 25 L 2 0 0 0 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

2 Operator is Limitorque SMB-4. Event due to key failure between motor pinion gear
3 and shaft. Motor, pinion gear, and key were replaced. Analysis of key by Limitorque
4 indicated they installed the wrong key material. Manufacturer to review operators
5 supplied to generate a list that required other than standard key. An updated LER
6 will report sampling procedure and inspection results based on Limitorque's response.

8 9 FACILITY % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
STATUS 30 31 Operator Observation
G 28 0 0 0 29 NA A 31
8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100
ACTIVITY CONTENT AMOUNT OF ACTIVITY LOCATION OF RELEASE
RELEASED OF RELEASE 35 36 NA NA
Z 33 Z 34 NA
8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100
PERSONNEL EXPOSURES
NUMBER TYPE DESCRIPTION 39
0 0 0 0 37 Z 38 NA
8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100
PERSONNEL INJURIES
NUMBER DESCRIPTION 41
0 0 0 0 40 NA
8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100
LOSS OF OIL DAMAGE TO FACILITY
TYPE DESCRIPTION 43
Z 42 NA
8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100
PUBLICITY
NUMBER DESCRIPTION 45
N 44 NA
8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

NRC USE ONLY

8106090548

NAME OF PREPARER Paul F. Doan

PHONE: 402-825-3811