

AMPHENOL NORTH AMERICA

Bunker Ramo Corporation
9201 Independence Ave. • Chatsworth, California 91311 • 213/341-0710

November 11, 1980

United States Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Attention: Mr. Karl V. Seyfrit
Director

Subject: NRC Docket No. 99900116/80-02
Dated October 24, 1980

BUNKER
RAMO

Gentlemen:


Quality Assurance has received subject Docket and is now in the process of reviewing and interpreting the same.

Quality Assurance Management received the Docket Report on October 30, 1980. This office will take the necessary actions to comply with the report. However, it will take more than 30 days from this date. Therefore, the writer is requesting an extension up to December 23, 1980.

Your cooperation in this matter will be appreciated.

Very truly yours,

BUNKER RAMO CORPORATION
Amphenol North America Division
SAMS Operations



Howard D. Wright
Quality Assurance Manager

HDW/clg