FORM NRC-991

## U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE			CENSEE ACKNOWLEDGMENTE REULI 1981	
Cambridge Diagnostic Center Nuclear Medicine 27285 West Warren Dearborn Heights MI 48127			U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region III 799 ROOSEVELT ROAD Glen Ellyn, Illinois 60137	
. 000	KET NUMBER(S)	4. LICENSE NUMBER	(5)	S. DATE OF INSPECTION
03013748 21-17974-01			June 1, 1981	
he in	PECTION FINDINGS  ISSPECTION WAS AN examination of the act ission's rules and regulations and the co we records, interviews with personnel, an	nditions of your license. The	e inspection consisted of s	o radiation safety and to compliance with the selective examinations of procedures and repre- ult of this inspection are as follows:
X	No items of noncompliance or uns	safe conditions were four	nd.	
The	following items of noncompliance r	elated to records, signs, a	and labels were found:	
	A. Rooms or areas were not prope	rly posted to indicate th	e presence of a RADIA	ATION AREA. 10 CFR 20.203(b) or 34.4
	<ol> <li>Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42</li> </ol>			
	C. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d)			
	D. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.2036			
	E. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2)			
	F. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted of made available. 10 CFR 20.206(b)			
	G. Form NRC-3 was not properly posted. 10 CFR 20.206(c)			
	H. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b)			
	1. Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 34.43(d)			
	J. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51			
	K. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(c)			
	L. Records of inventories were no	t maintained. 10 CFR 34	4.26	
	M. Utilization logs were not maint	ained, 10 CFR 34.27		
	N. F.ecords of radiation survey ins	trument calibration were	e not maintained. 10 C	FR 34.24 I607
	). Records of teletherapy electric	al interlock tests were no	ot maintained as prescri	ibed in your license.
G	P. Other			
		Ely	n & Mats	enter)
	e NRC Inspector has explained a	and I understand the it	ems of noncompliance	
по	ncompliance will be corrected wi	thin the next 30 days.		