

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | I | L | Z | I | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33

CON'T  
01 | L | 0 | 5 | 0 | 0 | 0 | 2 | 9 | 5 | 7 | 0 | 5 | 2 | 7 | 8 | 1 | 8 | 0 | 6 | 0 | 5 | 8 | 1 | 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | While performing PT-12, Heater Failure Alarm was discovered on circuit |  
03 | 61008; investigation disclosed its redundant circuit was also inopera- |  
04 | ble. Red phone call was initiated at 1000 hrs. per Tech. Spec. Section |  
05 | 3.8.1.E.3 and 6.6.2.a(2) and unit shutdown was begun. Work Request Z- |  
06 | 12087 was issued, and after one circuit was returned to service unit |  
07 | shutdown was suspended at 1105 hrs. Second circuit was then repaired. |  
08 | The health and safety of the public was not affected. |

09 | P | C | 11 | D | 12 | Z | 13 | H | E | A | T | E | R | 14 | Z | 15 | Z | 16 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20  
17 | LER/RO REPORT NUMBER | 8 | 1 | 21 | 22 |  
18 | ACTION TAKEN | A | 18 | G | 19 | B | 20 | Z | 21 | 0 | 0 | 0 | 1 | 22 | N | 23 | Y | 24 | X | 25 | C | 2 | 6 | 8 | 26 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | This event was caused during unit one BIT changeout, when 208V Nelson |  
11 | heat trace was replaced with 120V Chemelex. Procedure deficiency |  
12 | caused two Chemelex 120V circuits to be connected to 208V. This caused |  
13 | a failure of the heat trace cable. This has not been a recurring prob- |  
14 | lem, new maint. procedures have been initiated no further action req. |

15 | E | 28 | 1 | 0 | 0 | 29 | NA | 30 | B | 31 | Operator Observation | 32 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

16 | Z | 33 | Z | 34 | NA | 35 | NA | 36 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

17 | 0 | 0 | 37 | Z | 38 | NA | 39 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

18 | 0 | 0 | 0 | 40 | NA | 41 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

19 | Z | 42 | NA | 43 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

20 | N | 44 | NA | 45 |  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER Steve Hazelrigg

PHONE: 312-746-2084 EXT 347

8106180534

9-74-1-15 0-0-0