



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
631 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

102

Docket Nos. 30-10467
30-10468

28 APR 1981



California State College
ATTN Dr. John Watkins, President
California, Pennsylvania 15419

Dear Dr. Watkins:

Subject: Inspection 81-01

This refers to the routine safety inspection conducted by Ms. J. Johansen of this office on April 3, 1981 of activities authorized by NRC License No. 37-10470-03 and 37-10470-02 and to the discussions of our findings held by Ms. Johansen with you and Dr. S. Hood of your staff at the conclusion of the inspection.

The inspection was an examination of activities conducted under your licenses as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of your licenses. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, measurements made by the inspector, and observations by the inspector.

Our inspector also verified the steps you have taken to correct the items of noncompliance and deviation brought to your attention in a letter and enclosure dated December 8, 1975. We have no further questions regarding the steps you took to correct items A and B of Appendix A. With regard to the item listed in Appendix B as a deviation this item was not corrected.

Based on the results of this inspection, it appears that one of your activities was not conducted in full compliance with NRC requirements, as set forth in the Notice of Violation, enclosed herewith as Appendix A. This item of noncompliance has been categorized into the levels described in the Federal Register Notice (45 FR 66754) dated October 7, 1980. You are required to respond to this letter and in preparing your response, you should follow the instructions in Appendix A.

Item A in the Notice of Violation enclosed with this letter was identified during a previous inspection of your licensed activities on November 19, 1975

8106180 151


28 APR 1981

and documented in the enclosure to our letter dated December 8, 1975. Your letter to this office dated February 2, 1976 stated you would calibrate your survey instruments as required. From our April 3, 1981 inspection it appears that the stated corrective actions were not implemented since this item remains uncorrected.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and your reply will be placed in the Public Document Room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,



John D. Kinneman, Chief, Materials
Radiological Protection Section,
Technical Inspection Branch

Enclosure:
Appendix A, Notice of Violation

cc: w/encl
Dr. Sam Hood, R.S.O.
Biology Department