

APPENDIX A

NOTICE OF VIOLATION

California State College  
California PA 15419

Docket No. 30-10467  
License No. 37-10470-03

As a result of the inspection conducted on April 3, 1981, and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violation was identified.

Condition 16 of your license requires that licensed material be possessed and used in accordance with statements, representations, and procedures contained in your application dated October 26, 1979 and letter dated February 19, 1980.

Attachment 3 of your application requires annual calibration of your survey meters with cobalt-60 sources.


Contrary to this requirement, as of the day of the inspection, April 3, 1981, your survey meters had not been calibrated since 1975.

This is a Severity Level IV Violation (Supplement VII).

Pursuant to the provisions of 10 CFR 2.201, California State College is hereby required to submit to this office within twenty-five days of the date of this Notice, a written statement or explanation in reply, including:

- (1) the corrective steps which have been taken and the results achieved;
- (2) corrective steps which will be taken to avoid further violations; and
- (3) the date when full compliance will be achieved. Under the authority of Section 182 of the Atomic Energy Act of 1954, as amended, this response shall be submitted under oath or affirmation.

Dated 28 APR 1981



John D. Kinneman, Chief  
Materials Radiological Protection  
Section

8106180 153