## U.S. NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT

1. LIGENSEE	ENSPECTION PHODING. IND LICENSEE ACKNOWLEDGMENT			
U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region IV 611 Ryan Plaza Drive, Suite 1000			on and Enforcement tive, Suite 1000	
Little Martina	8-1741	Arlington, Texas		
3. DOCKET NUMBER(S)	4. LICENSE HUMBER(S)	•	DATE OF INSPECTION	
一九14574	1-2-1-102-0		June 4, 1981	
6. INSPECTION FINDINGS  The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:				
No items of noncompliance or unsafe conditions were found.				
The following items of noncompliance related to records, signs, and labels were found:				
A. Rooms or areas were not properly posted to indicate the presence of a RADIATION AREA. 10 CFR 20.203(b) or 34.42				
B. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA.  10 CFR 20.203(c) (1) or 34.42				
C. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA.  10 CFR 20.203(d)				
D. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e)				
E. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL.  10 CFR 20.203(f) (1) or (f) (2)				
F. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b)				
G. Form NRC-3 was not properly	G. Form NRC-3 was not properly posted. 10 CFR 20.206(c)			
H. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20401(apor 34133(b)				
Records of surveys or disposes were not properly maintained. 10 CFR 20.401(b) or 34(e3(d) RLUL 1081 =				
Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained in 10 CFR 30.51, 40.61 or 70.51				
10 CFR 30.51, 40.61 or 70.51  R. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(a)  L. Records of inventories were not maintained. 10 CFR 34.26				
L. Records of inventories were not maintained. 10 CFR 34.26				
M. Utilization logs were not maintained 10 CFR 34.27				
N. Records of radiation survey instrument calibration were not maintained. 10 CFR 34.24				
O. Records of teletherapy electrical interlock jeste were not maintained as prescribed in your license.				
P. Other				
	Athe the	NRC 1 sector	the pull	
7. The NRC Inspector has explained a noncompliance will be corrected wi		f nondompliance list	ed above. The items of	
June 4. 1981	Melven D. R.	when S	enior Deciquer	
(Date)	- Again	Licensee Representative	- Title or Position	
		DAAL	AMINIAIAI	

ORIGINAL TO LICENSEE

8106300262

PUUK UKIGINAL