## U.S. NUCLEAR REGULATORY COMMISSION

OFFICE OF INSPECT. . AND ENFORCEMENT



## INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

1. LICENSE			ent de la companie de		
Radi	ingham Memorial Hospit otherapy Department isonburg, Virginia 22				
				203	
3. DOCKET	NUMBER(S)	4. LICENSE NUMBER(S		S. DATE OF INSPECTION	
030-00517		45-05594-02			
The inspect	tion FINGINGS tion was an examination of the acti n's rules and regulations and the cor cords, interviews with personnel, and	iditions of your license. The	inspection consisted of sele-	adiation safety and to compliance with the ctive examinations of procedures and repre- of this inspection are as follows:	
No	items of noncompliance or uns	afe conditions were found	i.		
The follo	owing items of noncompliance re	elated to records, signs, an	d labels were found:		
□ A.	Rooms or areas were not proper	rly posted to indicate the	presence of a RADIATI	ON AREA. 10 CFR 20.203(b) or 34.42	
□ в.	B. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42				
□ c.	C. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d)				
□ D.	Rooms or areas were not proper	rly posted to indicate the	presence of RADIOACT	TIVE MATERIAL. 10 CFR 20.203(e)	
□ E.	E. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2)				
□ F.	A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b)				
☐ G.	Form NRC-3 was not properly p	posted. 10 CFR 20.206(c	)		
□ н.	Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b)				
□ 1.	Records of surveys or disposals	were not properly mainta	ined. 10 CFR 20.401(b	) or 34.43(d)	
□ J.	ecords of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained.  O CFR 30.51, 40.61 or 70.51				
□ K.	Records of leak tests were not r	maintained as prescribed i	n your license, or 10 CF	R 34.25(e) 19119	
□ L.	Records of inventories were not	maintained. 10 CFR 34.	26	S AFTERIORS	
□ M.	Utilization logs were not mainta	ained. 10 CFR 34.27		94 11111 20 100	
□ N.	Records of radiation survey inst	trument calibration were	not maintained. 10 CFR	34.24 U.S. NUCLUS SOCIATION	
□ o.	Records of teletherapy electrica	al interlock tests were not	maintained as prescribe	ed in your license.	
□ P.	Other			-10	
			374	(a) 1:10	
			(NRC Inspect	tor)	
	RC Inspector has explained a npliance will be corrected wi		THE RESERVE AND PARTY AND PARTY AND PARTY AND PARTY AND PARTY.		
	(Date)		(Licensee Representati	me - Title or Position)	

ORIGINAL TO LICENSEE

POOR ORIGINAL