

OMB/LER

June 19, 1981

Mr. James G. Keppler Regional Director Office of Inspection and Enforcement Region III U.S. Nuclear Regulatory Commission Glen Ellyn, Illinois 60137

Reference: Zion Generating Station

Docket No. 50-295/DPR-39

Technical Specification, Section 6.6.2

Dear Mr. Keppler:

Enclosed please find Reportable Occurrence Report No. 50-295/81-24 for Zion Generating Station.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 6.6.2.b.(2), which states that conditions leading to operation in a degraded mode permitted by a limiting condition for operation or plant shutdown required by a limiting condition for operation require a 30 day written report.

This occurrence is the subject of a departmental investigation, and an updated LER will be submitted upon resolution.

Very truly yours,

K. L. Graesser Superintendent Zion Station

cc: J. Kohler/J. Waters

Enclosure: Reportable Occurrence Report No. 50-295/81-24

2639