

CONTROL BLOCK: 

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	3	1	1	7	0	5	2	3	8	1	8	0	6	1	9	8	1	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

DOCKET NUMBER

EVENT DATE

REPORT DATE

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

0 2 | While performing surveillance on May 23, 1981, Diesel Generator 2C tripped on

0 3 | overcurrent. The Diesel Generator was declared inoperable and Action Statement

0 4 | 3.8.1.1.a was entered at 0126 hours. Similar occurrences: 80-02, 80-22, 80-31,

0 5 | 81-02, 81-16.

0 6 |

0 7 |

0 8 |

7 8 9

COMP VALVE

7 8 9		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP SUBCODE		VALVE SUBCODE	
0 9		E E		E		E		E N G I N E				Z		Z	
7 8		9 10		11		12		13		14				15 16	
		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.					
(17) LER/RO REPORT NUMBER		8 1		0 2 6		0 3		L		0					
21 22		23		24 26		27		28 29		30		31		32	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER	
Z		Z		Z		Z		0 0 0 0		Y		N		L	
18 19		20		21		22		23		24		25		26	
37		40		41		42		43		44		47			

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS	
1 0	The overcurrent trip was caused by unexplained voltage spikes on the system grid.
1 1	The surveillance was performed satisfactorily. The Action Statement was terminated
1 2	at 0600 hours on May 23, 1981.
1 3	
1 4	

7 8 9 FACILITY STATUS 10 11 12 13 OTHER STATUS (30) METHOD OF DISCOVERY (31) DISCOVERY DESCRIPTION (32)

1 5 [E] (28) 0 0 0 (29) N/A B (31) Operator Observation 80

7 8 9 ACTIVITY CONTENT 10 11 12 13 RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 [Z] (33) [Z] (34) NA NA LOCATION OF RELEASE (36)

44 45 46 80

PERSONNEL EXPOSURES		TYPE		DESCRIPTION
NUMBER				
1	7	0	0	NA

PERSONNEL INJURIES  
NUMBER DESCRIPTION (41)  
1 8 9 10 11 12 NA 80

		LOSS OF OR DAMAGE TO FACILITY		(43)
		TYPE	DESCRIPTION	
1	9	2	NA	

80

NRC USE ONLY

PUBLICITY  
ISSUED DESCRIPTION (45)  
2 0 N (44) NA 68 69 80