



UNITED STATES
 NUCLEAR REGULATORY COMMISSION
 REGION V
 1990 N. CALIFORNIA BOULEVARD
 SUITE 202, WALNUT CREEK PLAZA
 WALNUT CREEK, CALIFORNIA 94596
 June 30, 1981

Docket No. 70-734 MATERIAL TRANSMITTED HEREWITH CONTAINS
 2.790 INFORMATION

General Atomic Company
 P. O. Box 81608
 San Diego, California 92138

Attention: Mr. H. N. Wellhouser, Director
 Nuclear Materials Control Division

Gentlemen:

This letter refers to the routine safeguards inspection of your activities authorized under NRC License No. SNM-696 conducted by Messrs. C. A. Schwan and E. J. Power of this office on June 15-19, 1981. It also refers to the discussion of our inspection findings held by the inspectors with you and other company representatives on June 19, 1981.

The inspection included examination of activities related to physical protection against radiological sabotage and against theft of special nuclear material in accordance with applicable requirements of Title 10, Code of Federal Regulations, Part 73, "Physical Protection of Plants and Materials", your Security Plan, and license conditions pertaining to physical protection as described in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and records, interviews with facility personnel and observations by the inspectors.

Within the scope of this inspection, no items of noncompliance were observed.

In accordance with Section 2.790(d) of the NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations, documentation of the findings of your safeguards and security measures are exempt from public disclosure; therefore, the enclosed inspection report will not be placed in the Public Document Room.

MATERIAL TRANSMITTED HEREWITH CONTAINS
 2.790 INFORMATION

IE03
 3
 //



General Atomic Company

-2-

June 30, 1981

MATERIAL TRANSMITTED HEREWITH CONTAINS
2.790 INFORMATION

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

for m S. Schuster
LeRoy R. Norderhaug, Chief
Safeguards Branch

Enclosure:

IE Inspection Report

No. 70-734/81-07 (IE-V-449)

cc w/enclosure:

J. Iles, Manager Security

W. Mowry, Licensing Administrator

MATERIAL TRANSMITTED HEREWITH CONTAINS
2.790 INFORMATION