



Reuter-Stokes

Reuter-Stokes, Inc.  
Edison Park  
8409 Darrow Road, Twinsburg, Ohio 44087  
216 425 3755, Ex. 425-4045

VTY-89-103  
December 28, 1989

XCOM1029  
11004236

Ms. Betty L. Wright  
Nuclear Commission  
Mail Station WF 1/3-H-4  
International Security  
Office of International Programs  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

Subject: Reshipment of Reuter-Stokes Fission Chamber  
RS-C3-2510-114 to Mexico for IAEA IC Project  
MEX/0/008/527C

Reference: XCOM1010 and Reuter-Stokes E-1151

Dear Ms. Wright:

As we discussed last week, attached is the application for a second export license to ship this detector to Salazar Nuclear Center, under the IAEA referenced above. Reuter-Stokes requests that the Department of State in the NRC use the same letter of assurance as furnished to us by the Mexican purchaser as was used for the original license.

This fission chamber was originally sent, using license XCOM1010 on April 29, 1988. The chamber was damaged in shipment and returned to Reuter-Stokes. Since the original license expired in April, 1989, we are applying for a new license. This will permit shipment of an identical fission chamber.

If there are any questions concerning this request, please call me at area code (216) 425-3755, extension 567.

Sincerely yours,

*Virginia T. Young*

Virginia T. Young  
Export Control Coordinator

VTY:if

Attachment

3 JAN 06