



A General Energy Company

Docket Number 50-346

License Number NPF-3

Serial Number 1752

January 5, 1990

DONALD C. SHELTON
Vice President - Nuclear
(419) 249-2300

United States Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Subject: Disposition of Human Engineering Discrepancy (HED) - 1988 Summary Report

Gentlemen:

During the November 28-30, 1989 NRC audit of Toledo Edison's Detail Control Room Design Review (DCRDR) Program, NRC's Audit Team requested the subject 1988 Summary Report be submitted. Accordingly, Toledo Edison hereby submits one copy of the report. The Summary Report contains copies of each of the 378 HEDs, which were dispositioned by the HED Special Study DCRDR Review Teams. The Report also contains background information, reference material, work summaries, component list, and other HED related information.

The Audit Team also requested that the addendum to the Summary Report be submitted. The addendum documents revisions to the original disposition of the HEDs while the Summary Report is to remain unchanged to document the original disposition of the HEDs. Toledo Edison will provide the addendum after the sixth refueling outage as agreed during the audit.

If you should have any questions concerning this matter, please contact Mr. R. W. Schrauder, Manager - Nuclear Licensing, at (419) 249-2366.

Very truly yours,

RTH/ssg

Attachment

cc: P. M. Byron, DB-1 NRC Senior Resident Inspector w/o
A. B. Davis, Regional Administrator, NRC Region III w/a
T. V. Wambach, DB-1 NRC Senior Project Manager w/o

9001160261 900105
PDR ADOCK 05000346
P FDC

A003
1/1