



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D. C. 20555

January 8, 1990

Docket No. 50-334
and 50-412

MEMORANDUM FOR: John F. Stolz, Project Director, PD I-4, Division of
Reactor Projects I/II, NRR

FROM: Peter S. Tam, Senior Project Manager, PD I-4, Division
of Reactor Projects I/II, NRR

SUBJECT: BEAVER VALLEY POWER STATION -- CLOSEOUT OF BULLETIN 89-02
(TAC 74221 and 74222)

By letter dated January 3, 1990, Duquesne Light Company responded to the subject bulletin regarding stress corrosion cracking of Anchor Darling valve bolting. In its letter, the licensee confirmed that the inspections requested by the bulletin have been performed, and replacements requested by the bulletin have been completed. Therefore, we consider this action complete, in accordance with instruction given in memorandum from Harry Rood, Lead PM, dated August 1, 1989.

By copy of this memorandum, Region I is advised of the licensee's actions to comply with the subject bulletin.

Peter S. Tam, Senior Project Manager
PD I-4, Division of Reactor Projects I/II

cc. Peter Wilson, senior resident inspector
PD I-4 reading file
Docket files
PDR and local PDR
H. Rood
T. McLellan
C. D. Sellers
N. P. Kadambi

9001170224 900108
PDR ADOCK 05000334
Q PDC