

January 17, 1990

Docket Nos. 50-454, 50-455, 50-456  
and 50-457

Thomas J. Kovach  
Nuclear Licensing Manager  
Commonwealth Edison Company  
OPUS West III  
1400 OPUS Place, Suite 300  
Downers Grove, Illinois 60515

Dear Mr. Kovach:

SUBJECT: BULLETIN 88-02, "RAPIDLY PROPAGATING FATIGUE CRACKS IN STEAM  
GENERATOR TUBES" - BYRON/BRAIDWOOD (TAC NOS. 67298 AND 67299)

By letters dated March 24 and April 8, 1988, you responded to Bulletin 88-02 for Byron and Braidwood Stations, Unit 1. (Unit 2 for Byron and Braidwood Stations have D-5 steam generators which do not require a response for the Bulletin.) We reviewed your response and found it acceptable with one exception: you did not state that your definition of denting was consistent with Item A of the Bulletin. This was corrected in your October 17, 1989 letter. Thus, we conclude that your responses to Bulletin 88-02 are acceptable.

Original signed by

Leonard N. Olshan, Project Manager  
Project Directorate III-2  
Division of Reactor Projects - III,  
IV, V and Special Projects

cc: See next page

DISTRIBUTION

<del>Docket File</del>	NRC & Local PDRs	DNeighbors
PDIII-2 r/f	LLuther	
LOlshan	SSands	
UGC	EJordan	
ACRS (10)	Plant File	

OFFICIAL RECORD COPY  
Document Name: KOVACH7

PDIII-2:LA	PDIII-2:PM	PDIII-2:PM	PDIII-2:PD
LLuther	LOlshan	SSands	JCraig
1/17/90	1/16/90	1/17/90	1/19/90

*P.S. For*

*DFOL  
1/10*



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D. C. 20555

January 17, 1990

Docket Nos. 50-454, 50-455, 50-456  
and 50-457

Thomas J. Kovach  
Nuclear Licensing Manager  
Commonwealth Edison Company  
OPUS West III  
1400 OPUS Place, Suite 300  
Downers Grove, Illinois 60515

Dear Mr. Kovach:

SUBJECT: BULLETIN 88-02, "RAPIDLY PROPAGATING FATIGUE CRACKS IN STEAM  
GENERATOR TUBES" - BYRON/BRAIDWOOD (TAC NOS. 67298 AND 67299)

By letters dated March 24 and April 8, 1988, you responded to Bulletin 88-02 for Byron and Braidwood Stations, Unit 1. (Unit 2 for Byron and Braidwood Stations have D-5 steam generators which do not require a response for the Bulletin.) We reviewed your response and found it acceptable with one exception: you did not state that your definition of denting was consistent with Item A of the Bulletin. This was corrected in your October 17, 1989 letter. Thus, we conclude that your responses to Bulletin 88-02 are acceptable.

A handwritten signature in cursive script that reads "Leonard N. Olshan".

Leonard N. Olshan, Project Manager  
Project Directorate III-2  
Division of Reactor Projects - III,  
IV, V and Special Projects

cc: See next page

Mr. Thomas J. Kovach  
Commonwealth Edison Company

Byron/Braidwood Power Station  
Units 1 and 2

cc:

Mr. Jack Tain  
Atomic Power Distribution  
Westinghouse Electric Corporation  
Post Office Box 355  
Pittsburgh, Pennsylvania 15230

Joseph Gallo, Esq.  
Hopkins and Sutter  
888 16th Street, N.W.  
Suite 700  
Washington, D.C. 20006

Regional Administrator  
U. S. NRC, Region III  
799 Roosevelt Road, Bldg. #4  
Glen Ellyn, Illinois 60137

Ms. Bridget Little Rorem  
Appleseed Coordinator  
117 North Linden Street  
Essex, Illinois 60935

Mr. Edward R. Crass  
Nuclear Safeguards and Licensing  
Division  
Sargent & Lundy Engineers  
55 East Monroe Street  
Chicago, Illinois 60603

U. S. Nuclear Regulatory Commission  
Resident Inspectors Office  
RR#1, Box 79  
Braceville, Illinois 60407

Mr. Thomas W. Ortziger, Director  
Illinois Emergency Services  
and Disaster Agency  
110 East Adams Street  
Springfield, Illinois 62706

Dr. Bruce von Zellen  
Department of Biological Sciences  
Northern Illinois University  
DeKalb, Illinois 61107

U. S. Nuclear Regulatory Commission  
Byron/Resident Inspectors Office  
4448 North German Church Road  
Byron, Illinois 61010

Ms. Lorraine Creek  
Rt. 1, Box 182  
Manteno, Illinois 60950

Mrs. Phillip B. Johnson  
1907 Stratford Lane  
Rockford, Illinois 61107

Douglass Cassel, Esq.  
109 N. Dearborn Street  
Suite 1300  
Chicago, Illinois 60602

Ms. Pat Morrison  
913 N Main Street #707  
Rockford, Illinois 61103-7058

David C. Thomas, Esq.  
77 S. Wacker Drive  
Chicago, Illinois 60601

Mr. Thomas J. Kovach  
Commonwealth Edison Company

- 2 -

Byron/Braidwood

cc:

Illinois Department of  
Nuclear Safety  
Office of Nuclear Facility Safety  
1035 Outer Park Drive  
Springfield, Illinois 62704

Michael Miller, Esq.  
Sidley and Austin  
One First National Plaza  
Chicago, Illinois 60690

George L. Edgar  
Newman & Holtzinger, P.C.  
1615 L Street, N.W.  
Washington, D.C. 20036

Commonwealth Edison Company  
Byron Station Manager  
4450 North German Church Road  
Byron, Illinois 61010