

JAN 22 1990

In Reply Refer To:
License: 35-26991-01
Docket: 30-31123/90-01

Anchor Stone Company
ATTN: Tommy Harrison
Radiation Safety Officer
3300 North Mingo Valley Expressway
Tulsa, Oklahoma 74116

Gentlemen:

Enclosed for your records is NRC Form 591, "Safety Inspection." Please note that no violations were observed during the January 12, 1990, initial inspection of your NRC Byproduct Material License 35-26991-01. No response to this letter is necessary.

During the inspection, the NRC inspector discussed with you: (1) the safety aspects of your licensed activities and compliance with regulatory requirements, (2) the NRC and DOT requirements, (3) the licensee's commitments made during the licensing process, and (4) the NRC enforcement policy.

If you have any questions concerning this matter, please call me at (817) 860-8100.

Sincerely,

Original Signed By:
CHARLES L. CAIN

Charles L. Cain, Chief
Nuclear Materials Inspection Section

Enclosure:
NRC Form 591

cc:
Oklahoma Radiation Control Program Director

bcc:
✓DMB - IE-07 *CLCain
RDMartin *ADGaines
ABBeach *MIS System
*NMIS *RIV Files (2)
LShea, RM/ALF (AR-2015) *RSTS Operator (Close Report)

*w/766

RIV:NMIS ADG
ADGaines/ch
1/19/90

C:NMIS CLC
CLCain
1/19/90

9001300120 900122
REG4 LIC30
35-26991-01 PDC

IE-07
1/0