

IAN 23 1990

In Reply Refer To:  
License: 35-19048-01  
Docket: 30-15283/90-01

Bill Miller, Inc.  
ATTN: Bill Miller, President  
P.O. Box 1107  
Henryetta, Oklahoma 74437

Gentlemen:

This refers to the routine, unannounced radiation safety inspection conducted by Mr. Anthony D. Gaines of this office on January 8, 1990, of the activities authorized by NRC Byproduct Material License 35-19048-01, and to the discussion of our findings held by the inspector with you and members of your staff at the conclusion of the inspection.

The inspection was an examination of the activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements, and observations by the inspector.

Please note that no violations or deviations were identified.

Should you have any questions concerning this letter, we will be pleased to discuss them with you.

Sincerely,  
*Original Signed By*

**A. B. BEACH**

A. Bill Beach, Director  
Division of Radiation Safety  
and Safeguards

cc:  
U.S. Nuclear Regulatory Commission  
ATTN: Regional Administrator, Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Oklahoma Radiation Control Program Director

bcc:  
DMB - Original (IE-07) RDMartin ABBeach  
Glenda Jackson OC/LFMB (4503) LAYandell \*CLCain  
\*WLFisher \*ADGaines \*NMIS  
\*MIS System \*RIV Files (2) \*RSTS Operator  
\*REHall, URFO

\*W/766

RIV:NMISC  
ADGaines:lm  
1/22/90

C:NMISC  
CLCain  
1/22/90

D:DRSS  
ABBeach  
1/22/90

9002010121 900123  
REG4 LIC30  
35-19048-01 PDC

IE-07  
110