

JAN. 22 1990

Docket No. 030-29882
EA No. 90-12

License No. 37-28004-01

TEI Analytical Service, Inc.
ATTN: Gary E. Weiss
Radiation Safety Officer
P.O. Box 534
Washington, Pennsylvania 15301

Gentlemen:

Subject: Special Inspection No. 030-29882/90-001

This refers to the inspection conducted on January 4, 1990 at 35 West Point Road, Washington, Pennsylvania by Messrs. David J. Collins and James P. Dwyer of this office, and associated telephone inquiries on January 17 and 18, 1990. Our review was conducted to examine the occurrence of a radiography incident and the performance of your radiation safety program. The inspection was an examination of your activities as they relate to radiation safety and to compliance with the Commission's regulations and the license conditions. The inspection consisted of observations by the inspector, interviews with personnel, and a selective examination of representative records. The findings were discussed with you at the conclusion of the inspection. A copy of the NRC inspection report is enclosed.

As discussed in a telephone conversation on January 19, 1990, between you and John R. White of this office, the apparent violations identified during this inspection will be the subject of an Enforcement Conference to be held at our office in King of Prussia, Pennsylvania at 2:00 p.m., on January 25, 1990. We understand that you and appropriate members of your staff will attend this meeting. The purposes of the Conference are to discuss the apparent violations, their root causes and safety significance; identify any errors in our inspection report; and provide any other information, including proposed corrective actions, which will help us determine the appropriate enforcement action. You should be prepared to discuss improvements in your management control system that will prevent recurrence of these types of violations.

Enforcement actions for these violations will be considered by the NRC following the conference. A copy of the NRC Enforcement Policy as described in Appendix C of 10 CFR Part 2 is enclosed for your information. Directions to the NRC Region I office are included.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosures will be placed in the Public Document Room.

OFFICIAL RECORD COPY

9002060231 900122
REG1 LIC30
37-28004-01 FDC

1E107

JAN. 22 1990

TEI Analytical

2

Your cooperation with us is appreciated.

Sincerely,

Original Signed By:
Malcolm R. Knapp
Malcolm R. Knapp, Director
Division of Radiation Safety
and Safeguards

Enclosures:


1. Inspection Report No. 030-29882/90-001
2. Directions to Region I Office
3. Appendix C of 10 CFR Part 2

cc:


Public Document Room (PDR)
Nuclear Safety Information Center (NSIC)
Commonwealth of Pennsylvania

bcc:


Region I Docket Room (w/concurrences)
Management Assistant, DRMA (w/o enclosures)
J. Lieberman, OE
J. Goldberg, OGC
R. Cunningham, NMSS
D. Holody, RI
K. Christopher, RI


RI:DRSS
Collins/bj


01/17/90


RI:DRSS
Dwyer


01/17/90


RI:DRSS
White

01/17/90


RI:DRSS
Bettenhausen

01/17/90


RI:DRSS
Knapp

01/17/90