



DOCKET NO. (6 digits) OR LICENSE NO. (BY PRODUCT) (13 digits)		REPOI NO.		MODULE NUMBER		VIOLATION SEVERITY OR DEVIATION		SITE RELATED	
03008794		8901		886740		1 2 3 4 5 6		A C B D	
				A					
				B					
				C					
				D					

VIOLATION OR DEVIATION (Enter up to 2400 characters for each item. If the text exceeds this number, it will be necessary to paraphrase. Limit lines to 50 characters each.)

2

3

4 License Condition 16 requires that licensed material be transported in accordance with the provisions of 10 CFR 71.5. 10 CFR 71.5(a) requires, in part, that transportation of licensed material be made in accordance with the applicable requirements of the Department of Transportation in 49 CFR 170-189.

5

6

7 49 CFR 173.448(a) requires that each shipment of radioactive materials be braced in order to prevent shifting during normal transportation.

8

9 Contrary to the above, as of September 28, 1989, packages containing radioactive materials transported in licensee vehicles were not so braced to prevent shifting.

10

11

12 This is a repeat violation.

13

14 This is a Severity Level IV violation. (Supplement V)

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

32

33

34

35

48