

DCD/DCB

FEB 6 1990

Lic. File 30-02264

Southeast Missouri Hospital
ATTN: Richard W. Meyer
Assistant Administrator
1701 Lacey Street
Cape Girardeau, MO 63701

License No. 24-00128-03; ~~24-044~~
License No. SNM-01595 70-2174

Gentlemen:

This refers to the routine safety inspection conducted by Mr. B. A. Parker of this office on January 18, 1990, of activities authorized by NRC Byproduct Material Licenses No. 24-00128-03 and SNM-01595, and to the discussion of our findings with you and members of your staff at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities under License No. 24-00128-03 appeared to be in violation of NRC requirements, as specified in the enclosed Appendix and a written response is required. No violations were identified for License No. SNM-01595.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC Public Document Room.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

R. J. Caniano, Chief
Nuclear Materials Safety
Section 2

Enclosure: Notice of Violation

cc w/enclosure:
DCD/DCB (RIDS)

RIII *(initials)*
Parker/gd
2/6/90

RIII *(initials)*
Caniano
2/6/90

9002220506 900206
REQ3 LIC30
24-00128-03 PNU

IE 07