

Enclosure 1

SALP 8

FINAL SALP REPORT

---

U. S. NUCLEAR REGULATORY COMMISSION

REGION III

---

SYSTEMATIC ASSESSMENT OF LICENSEE PERFORMANCE

50-295/89001; 50-304/89001  
Inspection Report Nos.

Commonwealth Edison Company  
Name of Licensee

Zion Station, Units 1 and 2  
Name of Facility

June 1, 1988 through September 30, 1989  
Assessment Period

9002260283 900209  
PDR ADOCK 05000295  
Q PNU

Zion Units 1 and 2

A. Summary of Meeting with Commonwealth Edison Company on January 4, 1990

The findings and conclusions of the SALP Board are documented in Report No. 50-295/89001; 50-304/89001 and were discussed with the licensee on January 4, 1990, at Zion, Illinois.

While the meeting was primarily a discussion between the licensee and NRC, it was open to members of the public as observers.

The following licensee and NRC personnel were in attendance.

Commonwealth Edison Company

B. Thomas, President  
C. Reed, Senior Vice President, Nuclear Operations  
T. J. Maiman, Vice President, PWR Operations  
K. L. Graesser, General Manager, PWR Operations  
T. Joyce, Plant Manager, Zion

Nuclear Regulatory Commission

A. B. Davis, Regional Administrator, RIII  
E. G. Greenman, Director, Division of Reactor Projects, RIII  
W. D. Shafer, Chief, Branch 1, Division of Reactor Projects, RIII  
J. M. Hinds, Chief, Section 2A, Division of Reactor Projects, RIII  
J. W. Craig, Director, Project Directorate III-1, NRR  
J. D. Smith, Senior Resident Inspector, Zion  
R. J. Leemon, Resident Inspector, Zion  
A. M. Bongiovanni, Resident Inspector, Zion

B. Comments Received from Licensee

Commonwealth Edison Company's January 25, 1990 response to the Zion Initial SALP 8 Report included several comments that have resulted in a minor revision to the Initial SALP Report. This change is listed in Enclosure (2), Revision sheet, and the revised page is included as Enclosure (3).

Replace the page in error listed in Enclosure 2 Revision Sheet, with the corrected page attached in Enclosure 3 into your copy of the Initial SALP Report. When corrected pages are included, the Initial SALP Report should be considered the Final SALP Report.

C. Regional Administrator's Conclusions Based on Consideration of Licensee Comments

I have concluded that the overall ratings in the affected areas have not changed.