

APPENDIX A

NOTICE OF VIOLATION

Process Technology of North Jersey
Rockaway, New Jersey 07866

Docket No. 030-07022
License No. 29-13613-02

As a result of the inspection conducted on December 18 and 19, 1989, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (Enforcement Policy) (1988), the following violation was identified:

Condition 26 of License No. 29-13613-02 requires that licensed material be possessed and used in accordance with statements, representations and procedures contained in an application dated June 3, 1987.

Item 10.2 E(2) of this application requires that prior to removal of any material from the shielded volume of the irradiator pool or storage pool that has been in close proximity to sealed sources, a radiation survey shall be conducted by a responsible individual to verify that source material or contamination is not being removed from the pool.

Contrary to the above, on December 18 and 19, 1989 the licensee did not conduct a radiation survey prior to removal of materials from the shielded volume of the storage pool.

This is a Severity Level IV violation. (Supplement VI)

Pursuant to the provisions of 10 CFR 2.201, Process Technology of North Jersey is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

9002270334 900205
REG1 LIC30
29-13613-02 PDC

OFFICIAL RECORD COPY

IR PROCESS - 0008.0.0
01/18/90

RETURN ORIGINAL TO
REGION I

IE:07