SAFETY INSPECTION

Deploca

CARRELINE DE L'ANTENNE DE L'ANTE	
accura Lab	e. Anc.
3888 W. 11	7th &
Meneland, De	hio '
3. DOCKET NUMBER(5)	4. LICEN

2. REGIONAL OFFICE

U.S. NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD GLEN ELLYN, IL 60137

3.	DOCKE	T	NUMBER(5)
		-	

SE NUMBER(S)

S. DATE OF INSPECTION

030-30775

34-25963-01

Licensee:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commissions (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews, with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

- 1. Within the scope of this inspection, no violations were observed.
- 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.
- 3. During this inspection certain of your activities, as checked below, were in violation of NRC requirements. THIS IS A NOTICE OF VIOLATION which is required to be posted in accordance with 10 CFR 19.11.

was not properly posted to indicate the presence . 10 CFR 20.203(b), (c), (d), (e) or 34.42. of a

were not properly labeled to indicate the presence of radioactive material. 10 CFR 20.203(f)(1), or (f)(2).

of sealed sources were not performed at the proper License Condition Number frequencies. 10 CFR __

were not properly maintained. D. Records of or License Condition Number ___

E. Documents were not properly posted or otherwise made evaluable. 10 CFR 19.11.

were not made in accordance F. Reports or notifications of or License Condition Number with 10 CFR_

hereby state that within 30 days the actions described by me to the inspector will be taken to correct the violations identified in the Items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by

> 9003010068 900109 REG3 L1C30 34-25963-01

SIGNATURE - LICENSEE